

Case Study #18

Client Category: Hydrocarbon contaminated soil
Location: Dade county, Florida, U.S.A.
Problem: An underground leaking motor oil storage tank went unnoticed and unemptied for 15 years.
Contamination Size: Two batches of excavated soil were contaminated with motor oil.

Batch #1 208 cubic yards **18,000 ppm**
Batch #2 178 cubic yards **8,530 ppm**

Custom Treatment: Soil was treated separately with 2 gallons of **Custom HC** per cubic yard. Nutrients were added according to recommendations and aeration was provided.

